



3. *Straight Lines around corners*

Engine Turning over 3D Shapes

The flexibility offered by using a guide to follow the surface means that unlike other machining processes which require precise geometric accuracy, engine turning can be done on absolutely any convex surface.



A highly domed cufflink with large ribs across it and a triangular cushion shaped key fob with ribs in two directions